


DIGITAL MULTIMETER PC20



Standard Accessory

1. Instruction Manual
2. Protective Holster (H-70)
3. Test Lead (TL-21)

Optional Accessory

1. Clamp Probe:CL-22AD, CL-20D, CL33DC
2. Temperature Probe:T-300PC
3. Soft case:C-C7
4. Carrying case:C-PC10/S
5. AC adapter:AD-71AC (100V), AD-72AC (220V)
6. RS-232C interface cable:KB-RS1
7. Clip adapter:CL-11
8. PC Link

Features

1. 4000 count display
2. Measuring data can be transferred to PC through RS232 cable with PC Link.
3. AC adapter is available for long time measurement.
4. Data hold, Range hold
5. Capacitance measurement
6. Safety cover for the 10A terminal to avoid miss insertion.
7. Tilt Stand
8. Holster for wall hanging and fixing test lead
9. ** RS232 cable, PC Link and AC adapter are optional.

General Specifications

Measuring Method	Sigma Delta
ADC display updates	3 times / sec
Display	Approx. 4000 counts in max.
Range Selection	Auto and Manual ranges
Over Display	"O.L" mark indication
Polarity	Automatic selection (only "-" is displayed)
Power Consumption	Approx. 8mW
Power Supply	R6 (1.5V)×2pieces
Fuse Protection	0.5A / 250V 5×20mm IR 300A 12A / 250V 6.3×30mm IR 500A
Dimension and weight	167(H)×90(W)×48(D)mm Approx 330g(including protective holster)
Safety	IEC1010-1 CATIII for 600V IEC1010-1 CATII for DC1000V / AC750V when AC adapter use:IEC1010-1 CATIII for 200V
EMC	EN50081-1 (EN55022), EN50082-1 (EN61000-4-2) EN50082-1 (EN61000-4-3), EN50082 (ENV50204)